



Attorney Docket No. 1594.1388

CJC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Ji Sick HWANG, et al.

Application No.: 10/790,701

ATTENTION

Confirmation No.: 4309

CERTIFICATE OF CORRECTION

Filed: March 3, 2004

BRANCH

U.S. Patent No.: 6,945,057

Batch No.:

Issued: September 20, 2005

For: ICE MAKER

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Certificate
MAY 23 2006

of Correction

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: May 19, 2006

By: 
Gene M. Garner, II
Registration No. 34,172

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

MAY 24 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,945,057

DATED : September 20, 2005

INVENTOR(S) : Ji Sick HWANG, et al.

On the cover page, (75) Inventors, change "Kwangiu" to --Kwangju-- for the first, second, third and fourth inventors.

On the cover page, (56) References Cited, U.S. Patent Documents, column 2, line 4, change "Mateck" to --Maleck--

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 6,945,057

No. of add'l copies
@ 50¢ per page



MAY 24 2006